



**Agusta AW139
XA-CPX
S/N 31063**



PROVISIONAL

2006 Agusta AW139 XA-CPX S/N 31063



OFFERED AT: Make Offer

2021 Interior
1,000 Hour Inspection Complete
No Known Damage History
Up to eight (8) Passenger Interior

TOTAL TIME: *Times as of October 31, 2022*

TOTAL TIME: 831.07

LANDINGS: 1591

ENGINES: (2) Pratt & Whitney Canada

PT6C-67C **ENGINE TIMES:** 831.07 / 831.07

ENGINE 1:

Comp Turbine cycles – 1,312

Power Turbine cycles – 1,575

ENGINE 2:

Comp Turbine cycles – 1,312

Power Turbine cycles – 1,575

MAINTENANCE PROGRAMS & INSPECTIONS STATUS



MAINTENANCE & INSPECTIONS

- Airworthiness Date: December 22, 2006
- Underwent 1,000-hour inspection at Hesa - Toluca
- RTS Nov. 3
- Maintenance Tracking by CAMP

Inspection:	Last Complied:	Next Due:
12 Month	c/w Nov 2022	Due Nov 2023
1000 Hour	c/w Nov 2022	

INTERIOR DESCRIPTION

2021 Corporate Interior (Aviation Completion Innovations)

Deluxe VIP Executive six (6) passenger interior features four (4) Aft facing chairs and two (2) Forward facing captain's chairs.

Two (2) Removeable 30G Jump Seats to allow for up to eight (8) passengers.

The cabin features include:

- Fwd row and Aft row seats
- Custom Executive VIP Cabin Interior
- Cockpit / Cabin Divider Bulkhead
- 2- Forward Facing VIP seats with arm rests – drawers between for additional storage
- 4 - Aft Facing VIP seats
- SRWPS (Sound Reduction Wall Panel System)
- Strategically installed Enhanced Sound Proofing (ACI Cocoon panels)
- 100% Wool carpet with Velero fastening system



Interior

INTERIOR PICTURES



Seats Facing Fwd



Seats Facing Aft

EXTERIOR

EXTERIOR DESCRIPTION

Overall upper Blue with white underside



This aircraft is being brokered by Guardian Jet, LLC. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Guardian Jet, LLC makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications subject to verification upon inspection. Aircraft subject to prior sale.

2021 07 28 /SS